14P.2 FORM ₆ 366 (12-81)	U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT	APPROVED BY OMB 3150-0011 EXPIRES 4-30-82
CONTROL BLOCK:	(PLEASE PRINT OR TYPE ALL F	REQUIRED INFORMATION)
	0 - 0 0 0 0 0 0 - 0 0 3 4 1 LICENSE NUMBER 25 3 4 1	0 0 0 4 57 CAT 58
CON'T 0	0 0 3 9 5 7 0 9 3 0 8 2 8 ET NUMBER 68 69 EVENT DATE 74	1 0 2 7 8 2 9
event description and probable 0 2 On September 30, 1982,	consequences (10) the Station entered Mode 3 with the	Pressurizer Relief
Tank Level indication (LI-470A) inoperable at the Control Room Evacuation Panel.		
0 4 This indication is required by Tech. Spec. 3.3.3.5; however, Specification 3.0.4		
o 5 is not applicable. There were no adverse consequences because the plant had not		
0 6 yet achieved initial criticality, and the Tech. Spec. Action Statement was		
0 7 complied with.		
08		
SYSTEM CAUSE CODE I D U E 7 8 10 11	CAUSE SUBCODE COMPONENT CODE SUBCO	15 Z 16
17 LER/RO EVENT YEAR 8 2	REPORT NO. O 1 1 O 3 L	No.
	THOOWN HOURS 22 ATTA CHMENT NPRD 4 Z 21 0 0 0 0	PRIME COMP. SUPPLIER N 25 R 3 6 9 43 44 47
CAUSE DESCRIPTION AND CORRECTION Due to defective ampli	VE ACTIONS ② fier and calibration circuit card, t	he transmitter would
1 not calibrate properly	. Also, the instrument reference le	g was not properly
1 2 filled. Corrective ac	tions were to replace the defective	circuit boards, fill
1 3 the reference leg, and	calibrate the instrument.	
1 4		90
1 5 B 28 0 0 0 29 N/A	B 31 Surveillance T	esting 32
1		OF RELEASE 36
7 8 9 10 11 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION	45 45	90
1 7 0 0 0 37 Z 38 N/A		80
PERSONNEL INJURIES NUMBER DESCRIPTION 41 1 8 0 0 0 40 N/A		
LOSS OF OR DAMAGE TO FACILITY (43)	8211060070 821027	80
1 9 Z 42 N/A	PDR ADOCK 05000395 S PDR	AID CLISE ONLY
2 0 N 44 N/A		NRC USE ONLY
NAME OF PREPARER	A. R. Koon, Jr. PHONE:	(803) 345-5209