

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M S G G S 1 2 0 0 - 0 0 0 0 - - 0 0 3 4 1 1 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T
01 REPORT SOURCE L 6 0 5 0 0 0 4 1 6 7 0 9 2 9 8 2 8 1 0 2 9 8 2 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 On September 29, 1982, smoke detector N515H alarmed in zone 1-15 (148 ft. elevation
03 of the Control Building) with no fire or smoke present. The smoke detector alarm
04 could not be reset. The fire zone was deactivated on the Security and Fire Protection
05 Computer. An hourly fire watch was established pursuant to T.S.3.3.7.9. There was no
06 effect on the health and safety of the public and no threat to plant safety. This
07 event is being reported pursuant to T.S.6.9.1.13.b. This is an interim report. The
08 final report will follow pending the completion of the investigation.
7 8 9 80

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
A B 11 C 12 Z 13 I N S T R U 14 E 15 Z 16
7 8 9 10 11 12 13 18 19 20
17 LER/RO REPORT NUMBER EVENT YEAR SHUTDOWN METHOD SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
8 2 21 22 — 23 0 9 8 24 26 / 27 0 3 28 29 L 30 — 31 0 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
X 18 Z 19 Z 20 Z 21 0 0 0 0 37 40 N 23 N 24 X 25 H 2 6 0 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The detector alarmed due to dust accumulation on the sensor. The detector was cleaned,
11 retested, and returned to service on October 1, 1982. A revised program for the smoke
12 detectors is under investigation to determine if an increased frequency of performance
13 of PM's would significantly reduce the number of smoke detector false alarms.
14
7 8 9 80

15 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32
B 28 0 0 0 29 NA 31 Alarm 32
7 8 9 10 12 13 44 45 46 80

16 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
Z 33 Z 34 NA 35 NA 36
7 8 9 10 11 44 45 80

17 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
0 0 0 37 Z 38 NA 39
7 8 9 11 12 13 80

18 PERSONNEL INJURIES NUMBER DESCRIPTION 41
0 0 0 40 NA 41
7 8 9 11 12 80

19 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43
Z 42 NA 43
7 8 9 10 80

20 ISSUED PUBLICITY DESCRIPTION 45
N 44 NA 45
7 8 9 10 80

8211060204 821029
PDR ADDCK 05000416
S PDR

NRC USE ONLY

NAME OF PREPARER Original signed by Ron Byrd PHONE: _____

GPO 81-7-926