

**DUKE POWER COMPANY**

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

October 27, 1982

TELEPHONE  
(704) 373-4531

Mr. J. P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1  
Docket No. 50-369

Dear Mr. O'Reilly:

Reportable Occurrence Report RO-369/82-72 was to have been submitted by October 27, 1982. This 30-day Reportable Occurrence (pursuant to Technical Specification 6.9.1.13) concerns Technical Specification 3.7.6 "Two Independent Control Area Ventilation Systems Shall Be Operable," which was violated on September 27, 1982. However, investigation of the incident and resolution of the problem is not yet complete. The complete report will be submitted by November 5, 1982.

Very truly yours,

*Hal B. Tucker* *lywan*

Hal B. Tucker

PBN:scs

cc: Director  
Office of Management and Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. P. R. Bemis  
Resident Inspector-NRC  
McGuire Nuclear Station

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway  
Suite 1500  
Atlanta, Georgia 30339

8211060210 821027  
PDR ADDCK 05000399  
S PDR

OFFICIAL COPY

IE 22

NOV 1 AID: 32  
NRC REGION II  
ATLANTA, GEORGIA