

October 29, 1982

Mr. R.C. Haynes Director, Region I U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION LICENSEE EVENT REPORT 82-024/01T-0 ER 100450 FILE 841-23 PLA- 1373

Docket No. 50-387 License No. NPF-14

Dear Mr. Haynes:

Attached please find a copy of Licensee Event Report No. 82-024/01T-0. This event was determined to be reportable per Technical Specification 6.9.1.8.h in that an unanalyzed single failure would cause a loss of cooling water flow to the Diesel Generators, resulting in their failure.

H.W. Keiser

Superintendent of Plant-Susquehanna

DGM/cw

cc: A. Schwencer
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington, DC 20555

G. Rhoads Resident Inspector U.S. Nuclear Regulatory Commission P.O. Box 52 Shickshinny, PA 18655

Terr