



UNIVERSITY OF MISSOURI

DKN 03000303

Radiation Safety Office

5184A Clark Hall  
Columbia, Missouri 65201  
Telephone: (314) 882-3721

October 21, 1982

Materials Radiation Protection  
Region III, U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Attn: D.G. Wiedeman  
Ref: License 24-00513-35  
License SNM-1799

Gentlemen:

In response to your letter of October 5, 1982, and the attached Notice of Violation dated September 29, 1982, please be advised of the following corrective action taken:

1. Rechargeable batteries for the radiation monitor have been replaced, and the monitor is now functioning properly.
2. In addition to the daily operational test performed by clinical personnel, a monthly test will be performed by a staff member from Health Physics Services, who will arrange for necessary repair.
3. Full compliance was achieved by October 18, 1982.

Relative to License SNM-1799, we have separately requested of the Materials Licensing Branch, Division of Fuel Cycle and Material Safety, that the License be terminated.

Sincerely,

John H. Tolan  
Radiation Safety Officer

JHT: mh

cc W. Volkert, Ph.D.  
R. Abadir, M.D.  
P. Lee, Ph.D.  
G. Ejigu, Ph.D.

8211060375 821028  
NMS LIC30  
24-00513-35 PDR

an equal opportunity institution

OCT 25 1982