SAFECULARIOS HECHMATION

The information on this page is considered to be appropriate for public disclosure pursuant to 10 CFR 2,790

U. S. NUCLEAR REGULATORY COMMISSION

REGION V

Report Nos.

50-528/90-50, 50-529/90-50, 50-530/90-50 (IE-V-936)

Docket Nos.

50-528, 50-529, and 50-530

License No.

NPF-41, NPF-51 and NPF-74

Licensee:

Arizona Nuclear Power Project

P.O. Box 52034

Phoenix, Arizona 85072-2034

Facility Name: Palo Verde Nuclear Generating Station, Units 1, 2 and 3

Inspection at: Wintersburg, Arizona

Inspection Conducted: October 29 through November 27, 1990

Inspectors:

Norderhaug, Senior Physical Security

Date Signed

Inspector

Approved by:

Robert J. Pate, Chief

det

Date Signed

Nuclear Materials and Fuel Facilities Branch

Summary:

Areas Inspected: This unannounced, routine inspection by region-based staff examined the following portions of the licensee's physical security program: Security Plan and Implementing Procedures; Security Organization; Records and Reports; Testing and Maintenance; Physical Barriers; Compensatory Measures; Access Control; Detection Aids; Alarm Stations; Personnel Training and Qualifications Plan. During the inspection, portions of Inspection Procedures 30703, 81018, 81022, 81038, 81042, 81054, 81064, 81070, 81074, 81078, 81084, 81501, 92700, 92701, 92702 and 92703 were used.

Results: In the areas inspected, the licensee's programs appeared generally adequate to accomplish their security objectives.

TENGLOSUFE CONTAINS SAFEGURDES INFORMATION. UPON STEPARATION THEE PAGE IS DECONTROLLED.

SAFEGUARDS INFORMATION