




LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

September 17, 1982

L. V. MAURIN
Vice President
Nuclear Operations

W3182-0040



Mr. G. L. Madsen
Reactor Projects Branch, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit 3
Supplemental Response to USNRC Inspection Report 50-382/Rpt. 82-10

REFERENCES: LP&L Letter W3K82-0435, dated July 21, 1982 to G. L. Madsen

In the above referenced letter, LP&L committed to submit a supplemental response to USNRC Inspection Report 82-10 by September 20, 1982. Presently installation inspections and evaluation of Safety-Related Instrumentation Systems, including the Steam Generator level instruments identified in USNRC Inspection Report 82-10, are in progress thus additional time will be necessary to define and/or implement appropriate corrective actions.

LP&L will issue a Supplemental Response to Audit 82-10 stating the status of corrective actions on or before November 15, 1982.

Very truly yours,

L. V. Maurin

LVM/WAC:keh

1001

8211060406 820917
PDR ADDCK 05000382
PDR
Q