


TEXAS UTILITIES GENERATING COMPANY

2001 BRYAN TOWER DALLAS, TEXAS 75201-3050

R. J. GARY
EXECUTIVE VICE PRESIDENT
AND GENERAL MANAGER

October 29, 1982
TXX-3589



Mr. G. L. Madsen, Chief
Reactor Project Branch 1
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76012

Docket Nos. 50-445
50-446

COMANCHE PEAK STEAM ELECTRIC STATION
AUXILIARY BUILDING CONCRETE FLOOR SLABS
FILE NO.: 10110

Dear Mr. Madsen:

On October 20, 1982, we verbally informed your Mr. R. G. Taylor of a deficiency regarding embedded rotafoam and plywood in the Auxiliary Building concrete floor slabs.

We have completed our investigation and concluded that the matter is not reportable under 10CFR50.55(e). Records supporting this determination are available for your Inspector's review at the CPSES site.

Very truly yours,

R. J. Gary
for R. J. Gary

RJG:eaq

cc: NRC Region IV - (0 + 1 copy)

Director, Inspection & Enforcement (15 copies)
U. S. Nuclear Regulatory Commission
Washington, DC 20555

LE 27

8211090126 821029
PDR ADOCK 05000445
S PDR