

NOV 3 - 1982

Docket No. 50-483

Union Electric Company
ATTN: Mr. Donald F. Schnell
Vice President - Nuclear
Post Office Box 149 - Mail Code 400
St. Louis, MO 63166

Gentlemen:

Thank you for your letter dated October 15, 1982, informing us of the steps you have taken to correct the noncompliance which we brought to your attention in Inspection Report No. 50-483/82-10 forwarded by our letter dated September 16, 1982. With regard to item No. 1 of the appendix, your response did not indicate that testing of the cracked penetrations included testing to assure that they met the requirements of the electrical and environmental requirements as stated in the original design criteria. Please provide this information for our review.

Your cooperation with us is appreciated.

Sincerely,

RC Knop for

R. L. Spessard, Director
Division of Project and
Resident Programs

cc: W. H. Weber, Manager, Nuclear
Construction
S. E. Miltenberger, Manager
Callaway

cc w/ltr dtd 10/15/82:
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Region IV
K. Drey
Ronald Fluegge, Utility Division
Missouri Public Service
Commission

RIII *Wescott*
Wescott/rl
11/1/82

RIII *Knop*
Knoplin
11/2/82

RIII *Knop*
Knop

RIII *Spessard*
Spessard *for*

IEO1