YALLEE ATOLIC ELECTICG GOLLPARY



1671 Worcester Road, Framingham, Massachusetts 01701

2.C.2.11 FYR 82-54

TO GER 2.790 IN: ORMANON J

June 2, 1982

United States Nuclear Regulatory Commission Office of Inspection and Enforcement Region I 631 Park Avenue King of Prussia, PA 19406

Attention: Mr. Ronald C. Haynes, Regional Administrator Office of Inspection and Enforcement Region I

References: (a) License No. DPR-3 (Docket 50-29)
(b) I&E Letter to YAEC, dated May 12, 1982
I&E Inspection No. 50-29/82-02
(c) YAEC Letter to USNRC, dated September 8, 1982 (FYR 81-131)
(d) I&E Letter to YAEC, dated September 30, 1981 (Amendment No. 70)

Subject: Response to Inspection No. 50-29/82-02

Dear Sir:

Reference is made to I&E Inspection No. 50-29/82-02 conducted by your Mr. R. J. Bailey on February 22-26, 1982 at the Yankee Atomic Electric Company Nuclear Power Station in Rowe, Massachusetts. The report made subsequent to that inspection identified one item that apparently was not conducted in full compliance with NRC requirements. In accordance with Section 2.201 of the NRC's "Rules and Practices," Part 2, Title 10 Code of Federal Regulations, we hereby submit in Attachment "A" our response to that item. This information in Attachment "A" is considered proprietary and should be withheld from public disclosure pursuant to 10 CFR 2.790.

We trust this information is satisfactory; however, should you have any further questions, please feel free to contact us.

Very truly yours,

YANKEE ATOMIC ELECTRIC COMPANY

Saymond J. Barry for

D. E. Moody Manager of Operations

/dad

Withhold Attachment

B211090379 B21103 PDR ADOCK 05000029 G PDF