

Appendix

NOTICE OF VIOLATION

Marquette General Hospital

License No. 21-05432-04

As a result of the inspection conducted on September 22, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

License Condition No. 24 requires that licensed material be possessed and used in accordance with statements, representations, and procedures contained in certain referenced applications and letters.

The referenced letter dated May 10, 1982, states in Exhibit F that the xenon-133 trap is to be tested on a monthly basis.


Contrary to the above, the xenon-133 trap has been used and not tested as required since June 1982.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective actions to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated

11/1/82

  
D. J. Sreniawski, Chief  
Materials Radiation Protection  
Section 2

8211090451 821102  
NMS LIC30  
21-05432-04 PDR