PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE PNO-II-90-79A

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by the Region II staff on this date.

FACILITY: Entergy Corporation Grand Gulf 1

Docket No. 50-416 Port Gibson, MS Licensee Emergency Classification:
Notification of Unusual Event
Alert

Site Area Emergency
General Emergency
Not Applicable

SUBJECT: Grand Gulf Recirculation Pump Shaft Crack (Reference PNO-II-90-79)

On December 18, 1990, following an increase in vibration on the 'B' Recirculation Pump, the reactor was shutdown. The licensee disassembled the 'B' pump and discovered that the shaft had a 150 degree circumferential thru-wall crack. The licensee is investigating the cause of the shaft crack. The 'A' recirculation pump shaft was disassembled and inspected, no cracks were detected. The licensee is working closely with Perry (BWR 6 with similar Recirculation Pumps) to identify any differences in the mode of operations of these pumps. Perry does not use a seal purge and their ATWS trip setpoint logic is different. Entergy is evaluating these differences. The licensee replaced both pump shafts. The plant restarted December 30, 1990, and tied onto the grid December 31, 1990.

The Licensee does not plant to make a press release.

This information is current as of 11:00 a.m. on December 31, 1990.

CONTACT: Floyd Cantrell - 841-5534

DISTRIBUTION:

One White M'land Nat'l Flint North Bank Bldg Regions MAIL TO: DCS (Original IE 34) Chairman Carr Region I DOT (Transportation Only) Comm. Rogers OIG Region II AEOD Comm. Curtiss Region III FAX TO: Comm. Remick NRC Ops Ctr LICENSEE (Corporate) 2:05 Region IV OGC Region V RII Resident 2110 OCA

GPA/SLITP/PA Nicholson Lane

Phillips Bldg ACRS

NRR NMSS OE

Street EWW ASLAP

5520: 12/31/90 @ 1:20 P.M. TO REGIONS AND HQ

DW

0 \\ T=3×