

Duke Power Company
Nuclear Production Dept
PO Box 1007
Charlotte, N.C. 28201-1007

M.S. TUCKMAN
Vice President
Nuclear Operations
(704) 273-3831



DUKE POWER

January 10, 1991

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Subject: Oconee Nuclear Station, Unit 2
Docket No. 50-270
1990 Refueling Outage

Gentlemen:

Attached is a copy of the Inservice Inspection Report for Oconee Unit 2 End of Cycle 11 Refueling Outage. This report is submitted pursuant to Oconee Technical Specifications 4.2, 4.17.6(b), and Section XI of the ASME Boiler and Pressure Vessel Code, Article IWA-6230.

Very Truly Yours,

M. S. Tuckman

M. S. Tuckman

PJN/40

Attachment

cc: w/o attachment

S. D. Ebner, Regional Administrator
U. S. Nuclear Regulatory Commission, Region II
101 Marietta Street, NW Suite 2900
Atlanta, GA 30323

L. A. Wiens, Project Manager
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
One White Flint North, Mail Stop 9H3
Washington, D. C. 20555

P. H. Skinner, Resident Inspector
Oconee Nuclear Station

ADAT
11

9101140276 910110
PDR ADOCK 05000270
Q PDR