Docket Nos.: 50-329 and 50-330

MEMORANDUM FOR: The Atomic Safety and Licensing Board for

Midland Plant, Units 1 and 2

FROM: Thomas M. Movak, Assistant Director

for Licensing Division of Licensing

SUBJECT: BOARD NOTIFICATION - IMPROPER CABLES (BN 82-115)

In accordance with NRC procedures regarding Board notifications, the enclosed information is considered to be material and relevant to quality assurance issues and intervenor's contentions regarding cable installation before the Board in the Midland OL hearing.

In order to resolve earlier questions of Class IE cable misrouting, the applicant had been requested by Region III to reinspect all Class IE cables. Also, in view of recent television broadcasts alleging unauthorized cable substitutions, the applicant verified cable size by checking the cable jacket inscriptions rather than the attached cable tags. The enclosed Preliminary Motification PMO-III-82-121 notes that during the course of these continuing :einspections, four out of approximately 500 Class IE cables reinspected as of October 28, 1982, have been reported to contain 14 gauge wire where 10 gauge wire is specified by the design requirements. The substituted cables feed four decay heat cooldown and return isolation valves, which are safety-related components. Additional information is included in the enclosed press release made by the applicant.

The applicant is continuing the reinspection of additional Class IE cables and will issue a report on the findings by November 27, 1982. We will provide this report and the associated NRC staff evaluation when completed.

Original signed by: Thomas M. Novak

Thomas M. Novak, Assistant Director for Licensing Division of Licensing

8211110477 821108 PDR ADOCK 05000329 S PDR

> Enclosures: As stated

cc: See next page

\*SEE PREVIOUS WHITE

OFFICE	LA:DL:LB#4	DL:LB#4	DL: ŁB#4	AD:DL	Q:DL	 ***************************************
SURNAME .	MDuncan	*DHood;eb		11	.DE. senhut	
DATE	11/4/82	*11/4/82	11/ 5 /82	11/.8/82.	.11/	 ********

DISTRIBUTION

Docket 50-329/330

NRC PDR L PDR

PRC SYSTEM

NSIC

LB#4 Reading File

EAdensam DHood

MDuncan TNovak/LBerry WJDircks, EDO(3) EChristenburg, OELD JScinto, OELD (1)

Attorney, OELD

ELJordan, DEQA: IE

JMTaylor, DRP: IE

RIII-Administrator

RMattson

SHanauer

HThompson

w/enclosure

MEMORANDUM FOR: The Atomic Safety and Licensing Board for MWilliams ABennette, OELD (2) HDenton/ECase

JYoungblood

DEisenhut/RPurple

PPAS

Docket Nos.: 50-329

and

50-330

Midland Plant, Units 1 and 2

Thomas M. Novak, Assistant Director ASchwencer

for Licensing

OM, OL

Division of Licensing

GKnighton RVol1mer

SUBJECT:

FROM:

BOARD NOTIFICATION - IMPROPER CABLES (BN 82-115)

In accordance with NRC procedures regarding Board notifications, the enclosed information is considered to be material and relevant to quality assurance issues and intervenor's contentions regarding cable installation before the Board in the Midland OL hearing.

In order to resolve earlier questions of Class IE cable misinstallations, the applicant had been requested by Region III to reinspect all Class IE cables. Also, in view of recent television broadcasts alleging unauthorized cable substitutions, the applicant verified cable size by checking the cable jacket inscriptions rather than the attached cable tags. The enclosed Preliminary Notification PNO-III-82-121 notes that during the course of these continuing reinspections, four out of approximately 500 Class IE cables reinspected as of October 28, 1982, have been reported to contain 14 gauge wire where 10 gauge wire is specified by the design requirements. The substituted cables feed four decay heat cooldown and return isolation valves, which are safety-related components. Additional information is included in the enclosed press release made by the applicant.

The applicant is continuing the reinspection of additional Class IE cables and will issue a report on the findings by November 27, 1982.

> Thomas M. Novak, Assistant Director for Licensing Division of Licensing

Enclosures: As stated

cc: See next page

DEFICE LA	:DL:LB#4	DL:LB#4	DL:LB#4	AD:DL	D:DL		
SURNAME MD	uncan md	DL:LB#4 DHood:eb	EAdensam	TMNovak	DEisenhut		
				1.1//82	.1.1//82	***************************************	

## DISTRIBUTION FOR BOARD NOTIFICATION

## Before the Atomic Safety and Licensing Appeal Board

Midland Units 1&2 OM & OL Docket Nos. 50-329/330

Christine N. Kohl, Esq. Dr. John H. Buck Thomas S. Moore, Esq. Charles Bechhoefer, Esq. Dr. Jerry Harbour Dr. Frederick P. Cowan Mr. James R. Kates Mr. Frank J. Kelley Ms. Marry Sinclair Michael I. Miller, Esq. James E. Brunner, Esq. Ms. Barbara Stamiris Mr. Wendell H. Marshall T. J. Creswell Lee L. Bishop, Esq. Steve J. Galder, P.E. Mr. Wayne Hearn Myron M. Cherry, P.C. Mr. Frederick C. Williams

Atomic Safety and Licensing
Appeal Panel
Atomic Safety and Licensing
Board Panel
Docketing and Service Section
Document Management Branch

## ACRS Members

Dr. Robert C. Axtmann Mr. Myer Bender Dr. Max W. Carbon Mr. Jesse C. Ebersole Mr. Harold Etherington Dr. William Kerr Dr. Harold W. Lewis Dr. J. Carson Mark Mr. William M. Mathis Dr. Dade W. Moeller Dr. David Okrent Dr. Milton S. Plesset Mr. Jeremiah J. Ray Dr. Paul G. Shewmon Dr. Chester P. Siess Mr. David A. Ward