

DISTRIBUTION
Docket No. 40-8550PDR
Region IV
URFO w/f
URFO r/f
TFleming
JFisher
HPettengill
JLinehan
RSmith
JCollins

OCT 28 1982

04008550010E

URFO:TEF
Docket No. 40-8550

MEMORANDUM FOR: Docket File No. 40-8550

FROM: Thomas E. Fleming, Project Manager
Licensing Section II
Uranium Recovery Field Office

SUBJECT: TELECON REGARDING NRC REGION IV INSPECTION FOR
TERMINATION OF HOLMES AND NARVER, INC.'S LICENSE
NO. SUA-1307

Procedures for retiring the Holmes and Narver, Inc. License No. SUA-1307 are documented in a memorandum dated July 2, 1982. These procedures include the requirement that a decontamination survey of equipment be submitted to NRC, Office of Inspection and Enforcement (IE) by Holmes and Narver, Inc. IE would then review their survey report and, if appropriate, conduct a closeout inspection of the facility to determine whether the equipment is ready for unrestricted use.

The following is the status of the termination of the Holmes and Narver, Inc. license according to the procedures in the above referenced memorandum as stated by Mr. Blair Spitzburg, IE, in a phone conversation on October 18, 1982.

1. Holmes and Narver, Inc. submitted a decontamination survey to IE.
2. Holmes and Narver, Inc. were notified by IE that the survey was not adequate and consequently agreed to provide a revised survey.
3. Mr. B. Spitzburg, IE, inspected the equipment in Tucson, Arizona during the week of October 12, 1982 and found radiation levels to be above regulation levels.

8211110599 821028
PDR ADOCK 04008550
C PDR

OFFICIAL DOCKET COPY

20625

OCT 28 1982

- 4. Mr. B. Spitzburg, IE, is currently going to contact Holmes and Narver, Inc. to instruct them to perform additional decontamination cleanup and survey.

The license will not be terminated until a report is received from IE indicating that adequate decontamination and verification surveys have been performed.

TF

Thomas E. Fleming, Project manager
 Licensing Section II
 Uranium Recovery Field Office

Approved by:

HJP

Harry J. Pettengill, Section Chief
 Licensing Section II
 Uranium Recovery Field Office

| | | | | | | | | |
|------|----------------|---------------|-------|------------|---|---|---|---|
| OFC | :URFO | <i>TF</i> | :URFO | <i>HJP</i> | : | : | : | : |
| NAME | :TEFleming:me: | HJPettengill: | : | : | : | : | : | : |
| DATE | :82/10/22 | :82/10/22 | : | : | : | : | : | : |