

APPENDIX A

NOTICE OF VIOLATION

Vermont Yankee Nuclear Power Corporation  
Brattleboro, Vermont 05301

Docket No. 50-271  
License No. DPR-28

As a result of the inspection conducted on June 23 - 25, 1982, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violation was identified:

10 CFR 71.62(c) requires the licensee to maintain Quality Assurance records during the life of the package, of monitoring, inspection, and auditing of work performance during maintenance and repair of the packaging.

Contrary to the above, as of June 25, 1982, the licensee had not maintained Quality Assurance records of monitoring, inspection, and auditing of work performance during maintenance and repair of shipping packages.

This is a Severity Level V violation (Supplement V).

Pursuant to the provisions of 10 CFR 2.201, Vermont Yankee Nuclear Power Corporation is hereby required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

Dated OCT 28 1982

OFFICIAL RECORD COPY

8211120228 821028  
PDR ADOCK 05000271  
Q PDR