



**Commonwealth Edison**

Zion Generating Station  
Shiloh Blvd. & Lake Michigan  
Zion, Illinois 60099  
Telephone 312/746-2084

November 5, 1982

Mr. James G. Keppler  
Regional Director  
Office of Inspection and Enforcement  
Region III  
U.S. Nuclear Regulatory Commission  
Glen Ellyn, Illinois 60137

Reference: Zion Generating Station  
Docket No. 50-295/DPR-39  
Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-295/82-35 for Zion Generating Station.

This report is submitted to you in accordance with the requirements of the Technical Specification, Section 6.6.2.b(1) which states that reactor protection system or engineered safety feature instrument settings which are found to be less conservative than those established by the technical specifications but which do not prevent the fulfillment of the functional requirements of affected systems require a 30 day written report.

Very truly yours,

K. L. Graesser  
Superintendent  
Zion Station

cc: J. Waters

Enclosure: Reportable Occurrence Report No. 50-295/82-35

8211120340 821105  
PDR ADOCK 05000295  
S PDR

NOV 8 1982

IE 20