

Appendix

NOTICE OF VIOLATION

Washington University Medical Center

License No. 24-00167-11

License No. 24-00063-10

As a result of the routine safety inspection conducted on October 19-26, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violations were identified:

License Condition 14.A of License No. 24-00063-10 (Teletherapy) and License Condition 14.C of License No. 24-00167-11 (Broad Scope) require that specific sealed sources be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to the above, (a) the cobalt-60 teletherapy source at Jewish Hospital was not leak tested between January and September 1979 (8 months), September 1979 and April 1980 (7 months), nor April and November 1980 (7 months); (b) brachytherapy sources at the Mallinckrodt Institute of Radiology were not tested between January and September 1979 (8 months); (c) brachytherapy sources at Jewish Hospital were not tested between February and October 1979 (8 months), nor October 1979 and May 1980 (7 months); and (d) the 1 millicurie cesium-137 dose calibrator check source at Jewish Hospital was not tested between January and July of 1980, 1981, and 1982 (7 months each).

These are Severity Level IV violations (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

11-9-82

Dated



D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1