



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

November 1, 1982

Mr. J. G. Keppler, Director
Region III
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Keppler,

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

On October 31, 1982 a thru wall defect was found on the C 12 inch recirculation system safe end to pipe weld joint.

This occurrence is being reported in accordance with Technical Specification 6.7.B.1.c. These indications will be documented as a revision to Monticello Reportable Occurrence 82-16 which was reported September 28, 1982. A resolution is being investigated. Monticello Reportable Occurrence 82-16 has been renumbered to 82-13. All future correspondence on this event will be reported as updates to 82-13.

Yours very truly,

W.A. Shamba
Plant Manager

WAS/akr

c: Director; Office of Management Information and Program
Control File

Copy sent by telecopy to Keppler

8211120379 821101
PDR ADOCK 05000263
S PDR

IE 22
NOV 8 1982