	• LICENSEE EVENT REPORT Attachment to AECM-82/53/ Page 1 of 1
"	CONTROL BLOCK: [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	M S G G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 5 CAT 58 5
ON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 4 1 6 7 1 0 1 1 8 2 8 1 1 0 9 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	During shutdown, while performing maintenance to pull additional cable into panel
0 3	1H13P614, a panel fire barrier was broken. In the event of a fire, this could have
0 4	allowed for the spread of the fire to adjacent cable. This had no effect on the
0 5	health and safety of the public and did not constitute a threat to plant safety. This
0 6	report is being submitted per T.S.3.7.7 and T.S.6.9.2.
0 7	
7 8	SYSTEM CAUSE CAUSE COMP. VALVE
0 9	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	LER/RO EVENT YEAR SEQUENTIAL REPORT NO. 17 PE NO. 17 PE NO. 17 PE NO. 18 2 2 23 24 26 27 28 29 30 31 32
	ACTION FUTURE EFFECT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB, SUPPLIER MANUFACTURER Z 9 9 9 9 9 20 33 37 40 41 23 W 24 Z 25 Z 9 9 9 9 9 20 20 21 21 21 21 21 21 21 21 21 21 21 21 21
10	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The fire barrier was broken to perform maintenance. Operations was notified prior to
11	the start of the work. In accordance with T.S.3.7.7, a LCO was entered and an hourly
1 2	fire watch was established. Upon completion of work, the fire barrier was resealed.
1 3	The LCO was lifted on October 25, 1982. This is being submitted as a final report.
1 4 8	9 80
	FACILITY STATUS 30 OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 D
	CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 Z 33 Z 34 NA NA LOCATION OF RELEASE 36 NA
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA
1 8	PERSONNEL INJURIES NUMBER DESCRIPTION (4) NA
7 8	USS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION I Z (42) NA
7 8	9 10 8211150299 821109 80
2 0	PDR ADDCK 05000416 NA S PDR
	NAME OF PREPARER Original signed by John M. Albert PHONE