

AKIN, GUMP, STRAUSS, HAUER & FELD

ATTORNEYS AT LAW

A PARTNERSHIP INCLUDING PROFESSIONAL CORPORATIONS

1333 NEW HAMPSHIRE AVENUE, N.W.

SUITE 400

WASHINGTON, D.C. 20036

(202) 887-4000

FAX (202) 887-4288

2100 ONE CONGRESS PLAZA

111 CONGRESS AVENUE

AUSTIN, TEXAS 78701

(512) 499-6200

3200 REPUBLIC BANK CENTER

700 LOUISIANA STREET

HOUSTON, TEXAS 77002

(713) 221-0101

4100 FIRST CITY CENTER  
1700 PACIFIC AVENUE  
DALLAS, TEXAS 75201-4618  
(214) 969-2800

1500 INTERFIRST PLAZA  
300 CONVENT STREET  
SAN ANTONIO, TEXAS 78205  
(512) 270-0800

WRITERS DIRECT DIAL NUMBER (202) 887-4500

April 19, 1989

CC

Lee Bettenhausen

John White

Jay Gutierrez

Dan Moody

FEDERAL EXPRESS

Malcolm R. Knapp, Director  
Division of Radiation Safety  
and Safeguards  
U.S. Nuclear Regulatory Commission  
Region I  
475 Allendale Road  
King of Prussia, Pennsylvania 19408

Re: Docket No. 030-07022  
Inspection and Report No. 030-07022/89-001

Dear Mr. Knapp:

Reference is made to your letter and enclosures to Mr. John Scandaliros, President of Radiation Technology, Incorporated, enclosing a copy of the Inspection Report referenced above. In your letter you have set an Enforcement Conference in King of Prussia at 10:00 a.m. on April 26, 1989. Please be advised that the undersigned as well as Mr. Robert Riley of this firm will be attending the Enforcement Conference as Counsel for the Licensee along with RTI personnel.

We look forward to meeting with you on April 26.

Sincerely,

*Roy P. Lessy, Jr.*  
Roy P. Lessy, Jr.

cc: J. Gutierrez, Esq.  
Regional Counsel

9101220264 900913  
PDR FOIA  
JONES90-334 PDR

B/11

April 28, 1989

Appendix A

OPERATING AND EMERGENCY PROCEDURES

- 3.6 Radiation Safety Audit Procedures ~~7/25/86~~ <sup>7/25/86</sup> (→)
- 3.7 Corrective Action System 7/25/86
- 3.9 Training - Scheduling & Reporting Guide 9/29/86
  
- 9.100 Irradiator Startup 4/21/89
- 9.101 Irradiator Shutdown Normal 7/17/86
- 9.102 Irradiator Interlock Testing 9/27/87
- 9.103 Module Transfer 7/17/86
- 9.104 Cell Pool Level Monitoring System 7/21/87
- 9.105 Dosimetry Issue and Use ~~2/12/86~~ 10/1/86
- 9.106 Radiological Post ~~2/12/86~~ 10/1/86
- 9.107 Shift Turnover Procedure ~~2/12/86~~ 10/1/86
  
- 9.200 Emergency Shutdown ~~2/12/86~~ 3/6/87
- 9.201 Excessive Radiation Exposure Emergency 7/17/86
- 9.203 Fire in Radiation Room Emergency 3/6/87
- 9.204 Accidental Release of Radioactive Materials to the Uncontrolled Area 7/17/86
- 9.205 Leaking Irradiator Source Determination ~~10/1/86~~ 5/11/88
  
- 9.300 Care and Use of Radiation Survey Equipment ~~7/17/86~~ 10/1/86
- 9.302 Water Sampling and Analysis ~~7/17/86~~ 10/1/86
- 9.304 Contamination Test of Inside of Shipping Containers
- 9.306 Ozone Concentration Quarterly Survey 1/31/87
  
- 9.402 Loading/Unloading of CL F-168 Shipping Containers 7/17/86
- 9.403 Loading/Unloading GE Model No. 1500 Shipping Containers
  
- 9.501 Resin Replacement 7/17/86
- 9.502 Resin Regeneration ~~7/17/86~~ 10/7/86
- 9.503 Annual Fire Test 7/17/86
- 9.504 Irradiator Source Movement Log 3/6/87
  
- 9.600 Notification Requirements to US/NRC 7/17/86
- 9.601 Defect Reporting Requirements USNRC 7/17/86
  
- 9.700 Irradiator Operator Certification 7/27/86
  
- 12.100 Preventative Maintenance System 10/31/88
  
- 13.1 Design Control ~~7/17/86~~ 10/1/86
- x 13.2 Facilities Changes - ~~from~~ <sup>from</sup> ~~the~~ <sup>the</sup> ~~original~~ <sup>original</sup> ~~design~~ <sup>design</sup> B/D