



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

November 12, 1982

JAMES P. McGAUGHY, JR
ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 3100
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Inoperability of Drywell
Post-LOCA Vacuum Breaker
Position Indicators
Reference: LER 82-107/03 L-0
AECM-82/547

When entering Mode 3 (from Mode 4), the requirements of T.S.3.6.5.c were not satisfied due to the drywell post-LOCA vacuum breaker position indicators not being operable. The inoperability was due to the position indicators having been removed. Attached is LER 82-107/03 L-0 with supplementary information.

Yours truly,

[Handwritten Signature]
FOR J.P. McGaughy, Jr.

JPM:sap
Attachment

- cc: Mr. N. L. Stampley (w/a)
- Mr. R. B. McGehee (w/o)
- Mr. T. B. Conner (w/o)
- Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

OFFICIAL COPY
EE22

8211170312 821112
PDR ADOCK 05000415
S PDR