

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | F | L | S | L | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

CON'T
0 1 | R | E | P | O | R | T | S | O | U | R | C | E | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 3 | 5 | 7 | 1 | 1 | 0 | 1 | 8 | 8 | 2 | 3 | 1 | 1 | 0 | 8 | 8 | 2 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 | DURING NORMAL TESTING AT 99% POWER THE PULSE COUNTING FUNCTION FOR CEA
0 3 | 41 WAS FOUND DELETED MAKING THE PULSE COUNTING POSITION INDICATION
3 4 | REQUIRED BY TS 3.1.3.3 INOPERABLE. THE FUNCTION WAS IMMEDIATELY RESTORED.
0 5 | THIS FUNCTION IS CONTROLLED BY THE PLANT COMPUTER AND IS ONE OF THE TWO
0 6 | POSITION INDICATIONS AVAILABLE. PUBLIC HEALTH AND SAFETY WAS NOT AFFECTED,
0 7 | THIS IS THE SECOND EVENT OF THIS TYPE. PREVIOUS EVENT WAS LER 82-044.

0 8 | _____ 30

0 9 | SYSTEM CODE: I 9, D 10; CAUSE CODE: A 11, A 12, A 13; COMPONENT CODE: I N S T R U 14; COMP SUBCODE: I 15; VALVE SUBCODE: Z 16
17 | LER/RO REPORT NUMBER: 8 21, 22; SEQUENTIAL REPORT NO.: 4 23, 24; OCCURRENCE CODE: 0 25, 26; REPORT TYPE: L 27, 28; REVISION NO.: 0 29, 30
ACTION TAKEN: H 31, 32; FUTURE ACTION: X 33, 34; EFFECT ON PLANT: Z 35, 36; SHUTDOWN METHOD: Z 37, 38; HOURS: 0 39, 40, 41, 42; ATTACHMENT SUBMITTED: N 43, 44; NPRO-4 FORM SUB: N 45, 46; PRIME COMP SUPPLIER: N 47, 48; COMPONENT MANUFACTURER: F 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 | THE CEA POSITION IS BELIEVED TO HAVE BEEN DELETED WHILE SETTING UP FOR
1 1 | THE MODERATOR TEMP COEFFICIENT TEST TWO DAYS EARLIER. METHODS OF ALERT-
1 2 | ING THE OPERATOR ARE BEING EXPLORED. OPERATORS HAVE BEEN INSTRUCTED TO
1 3 | RUN A DELETION LOG FOLLOWING READJUSTMENT OF CEA POSITIONS.

1 4 | _____ 30

1 5 | FACILITY STATUS: E 23, 24; % POWER: 0 25, 26, 27, 28; OTHER STATUS: NA 29, 30; METHOD OF DISCOVERY: 8 31, 32; DISCOVERY DESCRIPTION: OPERATOR OBSERVATION 33, 34, 35, 36, 37, 38, 39, 40

1 6 | ACTIVITY CONTENT RELEASED OR RELEASE: 2 33, 34; AMOUNT OF ACTIVITY: NA 35, 36; LOCATION OF RELEASE: NA 37, 38, 39, 40

1 7 | PERSONNEL EXPOSURES NUMBER: 0 33, 34; TYPE: Z 35, 36; DESCRIPTION: NA 37, 38, 39, 40

1 8 | PERSONNEL INJURIES NUMBER: 0 33, 34; DESCRIPTION: NA 35, 36, 37, 38, 39, 40

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE: Z 33, 34; DESCRIPTION: NA 35, 36, 37, 38, 39, 40
8211170458 821108
PDR ADOCK 05000335
S PDR

2 0 | PUBLICITY ISSUED: N 33, 34; DESCRIPTION: NA 35, 36, 37, 38, 39, 40

NAME OF PREPARER: B. M. Parks PHONE: (305)456-3550 ext.364