UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50-219 UNIT NAME Oyster Creek DATE March, 1990 COMPLETED BY R. Baran TELEPHONE 971-4640

REPORT MONTH February, 1990

IONS/COMMENTS
epair the seal
serted after the tion System was ated.

Summary .

(1) REASON

- b. Maintenance or Test
- c. Refueling
- d. Regulatory Restriction
- a. Equipment Failure (Explain) e. Operator Training & License Exam

 - f. Administrative g. Operational Error (Explain)
 - h. Other (Explain)

(2) METHOD

- 1. Manual
- 2. Manual Scram
- 3. Automatic Scram
- 4. Other (Explain)

PDR ADOCK 05000219