

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50-219
 UNIT NAME Oyster Creek
 DATE July, 1990
 COMPLETED BY R. Baran
 TELEPHONE 971-4640

REPORT MONTH June, 1990

NO.	DATE	TYPE F: Forced S: Scheduled	DURATION (Hours)	REASON (1)	METHOD OF SHUTTING DOWN THE REACTOR OR REDUCING POWER (2)	CORRECTIVE ACTIONS/COMMENTS
98	900625	F	137.7	A	3	Automatic full scram due to main condenser low vacuum. Low vacuum caused by a loss of circulation water when backwash valve V-3-18 failed to open during condenser backwashing.

Summary :

(1) REASON

- | | |
|--------------------------------|-------------------------------------|
| a. Equipment Failure (Explain) | e. Operator Training & License Exam |
| b. Maintenance or Test | f. Administrative |
| c. Refueling | g. Operational Error (Explain) |
| d. Regulatory Restriction | h. Other (Explain) |

(2) METHOD

1. Manual
2. Manual Scram
3. Automatic Scram
4. Other (Explain)

9101230284 910115
 PDR ADDCK 05000219
 PDR