

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50-219
 UNIT NAME Oyster Creek
 DATE August, 1990
 COMPLETED BY R. Garar
 TELEPHONE 971-4640

REPORT MONTH July, 1990

NO.	DATE	TYPE		DURATION (Hours)	REASON (1)	METHOD OF SHUTTING DOWN THE REACTOR OR REDUCING POWER (2)	CORRECTIVE ACTIONS/COMMENTS
		F: Forced	S: Scheduled				
98	900625	F		94.1	A	3	Automatic full scram due to main condenser low vacuum. Low vacuum caused by a loss of circulation water when backwash valve V-3-18 failed to open during condenser backwashing.

9101230285 910115
 PDR ADDCK 05000219
 R

Summary :

(1) REASON

- a. Equipment Failure (Explain)
- b. Maintenance or Test
- c. Refueling
- d. Regulatory Restriction

- e. Operator Training & License Exam
- f. Administrative
- g. Operational Error (Explain)
- h. Other (Explain)

(2) METHOD

- 1. Manual
- 2. Manual Scram
- 3. Automatic Scram
- 4. Other (Explain)