



Commonwealth Edison
Zion Generating Station
Shiloh Blvd. & Lake Michigan
Zion, Illinois 60099
Telephone 312/746-2084

DMB

November 12, 1982

Mr. James G. Keppler
Regional Director
Office of Inspection and Enforcement
Region III
U.S. Nuclear Regulatory Commission
Glen Ellyn, Illinois 60137

Reference: Zion Generating Station
Docket No. 50-304/DPR-48
Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-304/82-28 for Zion Generating Station.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.b.(1) which states that reactor protection system or engineered safety feature instrument settings which are found to be less conservative than those established by the technical specifications but which do not prevent the fulfillment of the functional requirements of affected systems require a 30 day written report.

Very truly yours,

K. L. Graesser
Superintendent
Zion Station

cc: J. Waters

Enclosure: Reportable Occurrence Report No. 50-304/82-28

8211190097 821112
PDR ADOCK 05000304
S PDR

NOV 15 1982

IEJZ