10 CFR 2.201	SAFETY IN	ISPECTION	
Department of the Treasury U.S. Customs Laboratory 630 Sansome Street, Rm. 1429 San Francisco, CA 94111		U.S. Nuclear Regulatory Commission Region V 1450 Maria Lane, Suite 210 Walnut Creek, CA 94596	
030-20455	04-23284-01		January 10, 1491
Licensee	To see the second secon	THE SHARE WAS A PERSON NAMED AS A PERSON NAMED A PERSON NAMED AS A PERSON NAMED AS A PERSON NAMED AS A	от фил (примет на 1000 городи во представа от воличнаци върхова во того, водине, пре обора положена довачава воли в в в 19 дой
those actions at this time.	is and the conditions of your el, and observations by the in ons were observed. taken to correct the violation	r license. The inspection inspector. The findings a ons identified during the	consisted of selective examinations of procedures is a result of this inspection are as follows:  [ast inspection. We have no further questions on
3. During this inspection certain of your activities THIS IS A NOTICE OF VIOLATION which			
		was not properly posted to indicate the presence 10 CFR 20.203(b), (c), (d), (e) or 34.42	
B. Containers located in labeled to indicate the presence of radioac			were not properly
frequencies 10 CFR			were not properly maintained
E. Documents were not properly posted or o			ID BY
F. Reports or notifications of			were not made in accordance
with 10 CFR	0	r License Condition Nun	
ord Following march	aborning the	for monetary months of they Would	August - September 1989 by
Dk 9101240083 9101	10		
04-23284-01	PDR		
I hereby state that within 30 days the actions described this statement of corrective actions is made in account the NRC.			he violations identified in the items checked above urther response will be submitted unless required by
Waster STONATURE - LICENSEE	DATE	SIGNATUR	E-NACINSPECTOR 0ATE