



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
788 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

DCD/ACB
(RIDS)

JAN 10 1991

Docket No. 50-454
Docket No. 50-455

Commonwealth Edison Company
ATTN: Mr. Cordell Reed
Senior Vice President
Opus West III
1400 Opus Place
Downers Grove, IL 60515

Gentlemen:

This refers to the routine safety inspection conducted by inspectors W. J. Kropp, R. N. Sutphin, W. Stearns, D. Calhoun and K. Shembarger of this office from November 15, 1990 through January 2, 1991, of activities at the Byron Station, Units 1 and 2, authorized by NRC Operating Licenses No. NPF-37 and No. NPF-66, and to the discussion of our findings with Mr. R. Pleniewicz and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

W. D. Shafer, Chief
Reactor Projects Branch 1

Enclosure: Inspection Report
No. 50-454/90024(DRP);
No. 50-455/90024(DRP)

See Attached Distribution

9101240091 910110
PDR ADDCK 05000454
Q PDR

230057

TEO
11

JAN 10 1991

Distribution

cc w/enclosure:

M. Wallace, Vice President,
PWR Operations

T. Kovach, Nuclear
Licensing Manager

T. Schuster, Nuclear Licensing
Administrator

R. Pleniewicz, Station Manager

D. Brindle, Regulatory Assurance
Supervisor

DCD/DCB (RIDS)

OC/LFDCB

Resident Inspectors, Byron,
Braidwood, Zion

Richard Hubbard

J. W. McCaffrey, Chief, Public
Utilities Division

Diane Chavez, DAARE/SAFE

A. Hsia, LPM, NRR

Robert Newmann, Office of Public
Counsel, State of Illinois Center