LICENSEE EVENT REPORT

LICENSEE EVENT REPORT
CONTROL BLOCK: [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 C A S O S 1 2 O O O O O O O O O
CON'T REPORT L 6 0 5 0 0 0 2 0 6 7 1 0 1 3 8 2 8 1 1 1 8 2 9
[0]2 Three lapses in fire watch coverage at SONGS-1 occurred as follows: On October 12,
[0]3 [1982, a fire watch temporarily left his post to talk to another fire watch; Un October
[0]4] [13, 1982, two fire watches were improperly secured due to radiography in the vicinity;
on October 20, 1982, a continuous fire watch was temporarily assigned as a roving fire
ole watch. There was no adverse effect on public health or safety.
07
7 8 9
SYSTEM CODE SUBCODE COMPONENT CODE SUBCODE SUB
TO REPORT NUMBER 2 23 24 26 27 28 29 30 31 32
ACTION FUTURE COMPONENT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. PRIME COMP. SUPPLIER SUPPLIER SUPPLIER VALUE OF SUPPLIER
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) [Three lapses in fire watch coverage were caused by inadequate fire watch supervision.
The fire watch who left his post was terminated. A memo was issued on October 13, 1982,
to all fire watches reiterating their responsibilities. Two supervisory positions were
added to fire watch program. On October 26, 1982 a memo was issued to clarify the
authority for release of fire watches.
FACILITY STATUS STATU
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA
PERSONNEL EXPOSURES NUMBER 1 7 0 0 0 37 Z 38 DESCRIPTION 39 NA NA 80
PERSONNEL INJURIES NUMBER O O O O O O O NA 7 8 9 11 12 80
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA 8211190116 821110 PDR ADDCK 05000204
ISSUED DESCRIPTION (45) NA NA NA NA NA NA NA NA NA N
NAME OF PREPARED H. B. RAY HB Pay NAME OF PREPARED 714/402-7700