

Dad/DCB

JAN 11 1991

Veterans Administration Lakeside  
Medical Center  
ATTN: Erwin Singer, M. D.  
Chief of Staff  
333 East Huron Street  
Chicago, IL 60611

License No. 12-02642-06  
Docket No. 030-01435

Gentlemen:

This refers to the routine safety inspection conducted by Mr. Gary L. Shear of this office on December 27, 1990 of activities authorized by NRC Byproduct Material License No. 12-02642-06 and to the discussion of our findings with Ira Lawrence, M. D. and other members of your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

In addition to the above areas, the inspector examined actions taken to correct a violation found during our August 11 and 12, 1986, inspection. We have no further questions regarding this matter.

During this inspection, certain of your activities appear to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

IE07  
11

Veterans Administration Lakeside  
Medical Center

2

JAN 11 1961

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Roy J. Caniano, Chief  
Nuclear Materials Safety  
Section 2

Enclosure: Notice of Violation

cc w/enclosure:  
DCD/DCB (RIDS)  
Eli Port, Radiation Safety Officer  
James W. Fletcher, M.D.  
Veterans Administration

R111

Shear/1h

R111

Caniano