



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

November 12, 1982

Mr. James G. Keppler, Regional Administrator
Directorate of Inspection and
Enforcement - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: LaSalle County Station, Units 1 and 2
RHR System Pressure Switches
10 CFR 50.55(e) Final Report 82-09
NRC Docket Nos. 50-373 and 50-374

Dear Mr. Keppler:

Commonwealth Edison notified your office on October 13, 1982 of a deficiency in accordance with 10CFR50.55(e) concerning pressure switches installed on the RHR system.

These components were furnished as part of the NSSS contract. General Electric Co. has reviewed the situation and has verbally indicated that the pressure rating mismatch is unique to the LaSalle site and further it appears isolated at LaSalle. These components serve a dual function. Their pressure rating was adequate for their primary function but during steam condensing mode of the RHR system, their ratings were inadequate.

The intended corrective action will be to install adequate pressure switches prior to fuel load for Unit 2. It is presently, anticipated that the components will be shipped to the site on or about December 10, 1982. It is expected that they will be installed on Unit 1 by February 1, 1983. As indicated this is considered a final report for LaSalle County Station Units 1 and 2.

Please address any questions on this matter to this office.

Very truly yours,

C. W. Schroeder 11/10/82

C. W. Schroeder
Nuclear Licensing Administrator

lm

cc: Director of Inspection and
Enforcement, Washington, D.C.
NRC Resident Inspector LSCS

5411N

8211190226 821112
PDR ADOCK 05000373
S PDR

IE 27
NOV 12 1982