

U.S. NUCLEAR REGULATORY COMMISSION
REGION I

Report No. 50-272/82-15
50-311/82-15

Docket No. 50-272 License No. DPR-70 Safeguards Group IV
50-311 DPR-75

Licensee: Public Service Electric and Gas Company

P. O. Box 570

Newark, New Jersey

Facility Name: Salem Nuclear Generating Station

Inspection At: Hancocks Bridge, New Jersey

Inspection Conducted: June 14-18, 1982

Date of Last Physical Security Inspection: January 11-15, 1982

Type of Inspection: Special, Announced Physical Protection

Inspectors: Lisa M. McKeown 10-27-82
for G. C. Smith, Physical Protection date
Inspector

Lisa M. McKeown 10-27-82
L. M. McKeown, Physical Protection date
Inspector

Approved by: A. T. Gody 10-27-82
A. T. Gody, Chief, Safeguards date
Section

Inspection Summary: Special, Announced Physical Protection Inspection
Conducted on June 14-18, 1982 (Combined Inspection Report Nos. 50-272/82-15
and 50-311/82-15).

This inspection was commenced as a result of non-strike related violations which were identified during an inspection of the licensee strike and post strike activities (Combined Inspection Report Nos. 50-272/82-09 and 50-311/82-11). The inspection involved 60 inspector hours onsite by two region based inspectors.

Areas Inspected: Included a review of the Security Plan and Implementing Procedures, Vital Area Physical Barriers, Lighting, and Access Control (Personnel and Vehicles).

Results: The licensee was found to be in violation of NRC requirements in the following areas:

1. Security Plan - Failure to notify the Commission prior to a change which degraded the security program.
2. Physical Barriers (Vital Area) - Failure to maintain the integrity of a vital area barrier.
3. Illumination - Failure to maintain 0.2 foot candles of illumination within the protected area.
4. Access Control (Personnel) - Failure to follow access control procedures.
5. Access Control (Vehicles) - Failure to control vehicles in the protected area.