



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

November 10, 1982

Mr. James G. Keppler, Regional Administrator
Directorate of Inspection and
Enforcement - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: LaSalle County Station Units 1 and 2
HFA Relay Assembly Cracking
Revised Final Report, LSCS 1 and 2
10 CFR 50.55(e) #81-02
NRC Docket Nos. 50-373 and 50-374

- References (a): L. O. DelGeorge letter to J. G. Keppler
dated September 11, 1982.
- (b): GE Service Information Letter #44,
Supplement 2 dated February 13, 1981.

Dear Mr. Keppler:

The purpose of this transmittal is to update information provided in Reference (a) relative to the HFA relay assembly cracking replacement program.

General Electric (NSSS-San Jose) has completed the replacement of lexan coils on all of the safety-related NSSS HFA relays for Units 1 and 2 with the exception of some Unit 2 relays that were damaged during construction. The remaining Unit 2 NSSS safety related relays will be replaced with new qualified relays.

General Electric (IS&E), contracted by Commonwealth Edison Company, has completed the replacement of lexan coils on all of the safety-related balance-of-plant HFA relays for Units 1 and 2, with the exception of four relays that were not upgraded due to a lack of qualified replacements. Reference (b) recommended that a periodic visual inspection program be established and maintained until such time as the relays are upgraded or replaced. Such a program will be implemented by LaSalle County Station by February 1, 1983.

8211190269 821110
PDR ADOCK 05000373
S PDR

IE27

NOV 12 1982

J. G. Keppler

- 2 -

November 10, 1982

If there are any questions in this matter, please contact this office. This is considered a final report for LaSalle County Station Units 1 and 2.

Very truly yours,

CW Schroeder 11/10/82

C. W. Schroeder
Nuclear Licensing Administrator

lm

cc: Director of Inspection and
Enforcement, Washington, D.C.
NRC Resident Inspector - LSCS

5412N