



SACRAMENTO MUNICIPAL UTILITY DISTRICT □ 6201 S Street, Box 15830, Sacramento, California 95813; (916) 452-3211

November 18, 1982

DIRECTOR DIVISION OF LICENSING  
ATTENTION DARRELL G EISENHUT  
OFFICE OF NUCLEAR REACTOR REGULATION  
U S NUCLEAR REGULATORY COMMISSION  
WASHINGTON DC 20555

DOCKET 50-312  
RANCHO SECO NUCLEAR GENERATING STATION  
UNIT NO 1  
CONGRESSIONAL REQUEST FOR INFORMATION CONCERNING  
STEAM GENERATOR TUBE INTEGRITY (GENERIC LETTER 82-22)

We have received your October 26, 1982 letter, which requested a large amount of information related to Steam Generator problems at Rancho Seco. After reviewing your request and evaluating our available resources, we find that the District will be unable to complete the tabulated information you requested in a time frame which would support the scheduled Congressional hearing date. This is due to the fact that a large amount of research would be required to answer all of your questions, and all available staff members are totally immersed in activities related to the upcoming refueling outage of Rancho Seco and efforts necessary to install numerous NRC mandated changes during that outage.

We would, however, like to remind you that, as required by our Technical Specifications, much of the information you have requested has been reported in Licensee Event Reports, Monthly Operating Reports, Special Reports, and annual radiation worker exposure summaries (Environmental Report), albeit in a different format. These reports do not generally include outage costs; currently, the District considers the cost of replacement power (assuming foreign oil is required) for Northern California electricity consumers to be approximately \$1.13 million per day. No major steam generator repairs are anticipated for the Rancho Seco Unit in the next five years.

*John J. Mittimoe*  
John J. Mittimoe  
General Manager

*A001*

8211230086 821118  
PDR ADDCK 05000312  
P PDR