JAN 23 1991

DOD

Docket No. 50-346

Toledo Edison Company ATTN: Mr. Donald Shelton Vice President Nuclear Edison Plaza 300 Madison Avenue Toledo, OH 43652

Gentlemen:

This refers to the routine safety inspection conducted by Mr. J. Foster of this office on January 14-18, 1991, of activities at the Davis-Besse Nuclear Power Station, authorized by NRC Operating License No. NPF-3, and to the discussion of our findings with T. Meyers and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

9101290063 910123 PDR ADDCK 05000346

Greger, Chief Reactor Programs Branch

Enclosure: Inspection Report No. 50-346/91004(DRSS)

See Attached Distribution

28000





PDR

TE 35

Toledo Edison Company

## Distribution

.

.

cc w/enclosure: L. Storz, Plant Manager DCD/DCB (RIDS) OC/LFDCB Resident Inspector, RIII James W. Harris, State of Ohio Robert E. Owen, Ohio Department of Health A. Grandjean, State of Ohio, Public Utilities Commission D. Bement, FEMA, RV