John D. O'Toole Vice President

Consolidated Edison Company of New York, Inc. 4 Irving Place, New York, NY 10003 Telephone (212) 460-2533

November 4, 1982

Re:

Indian Point Unit No. 2 Docket No. 50-247 LER-82-043/03L-0

Mr. Ronald C. Haynes, Regional Administrator-Region I U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, Pa. 19406

Dear Mr. Haynes:

The attached Licensee Event Report LER-82-043/03L-0 is hereby submitted in accordance with the requirements of Technical Specification 6.9.1.7. This event is of the type described in Technical Specification 6.9.1.7.2.b.

Three copies of this letter and the attachment are enclosed as required.

Very truly yours, Mum D. VeTorle

IELL

attach. cc:

Mr. Richard DeYoung, Director (30 copies)Office of Inspection and Enforcementc/o Distribution Services Branch, DDC, ADMU. S. Nuclear Regulatory CommissionWashington, D. C. 20555

Mr. William G. McDonald, Director (3 copies) Office of Management Information and Program Control c/o Distribution Services Branch, DDC, ADM U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Mr. Thomas Foley, Senior Resident Inspector U. S. Nuclear Regulatory Commission P. O. Box 38 Buchanan, New York 10511

8211230213 821104 PDR ADDCK 05000247 S PDR