



November 15, 1982  
L-82-508

Mr. James P. O'Reilly  
Regional Administrator, Region II  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

NOV 19 11:08  
NRC REGION II  
ATLANTA, GEORGIA

Dear Mr. O'Reilly:

Re: St. Lucie Unit 2  
Docket No. 50-389, 10 CFR 50.55(e), 82-019  
Bent Small Bore Piping Not Inspected

On October 13, 1982, Florida Power and Light (FPL) notified NRC, Region II of a potential 10 CFR 50.55(e) condition existing at St. Lucie 2 site involving inspection of approximately 240 small bore (2" and under) piping bends. FPL is presently evaluating this item, and will inspect the affected pipe bends. FPL will complete these inspections and submit a final response to this item by December 30, 1982.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems and Technology

REU/cab

cc: Director of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

OFFICIAL COPY  
IE 27

8211230214 821115  
PDR ADOCK 05000389  
S PDR