



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

November 16, 1982

JAMES P. McGAUGHY, JR.
ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 3100
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
LPCS Inoperable Due to the Low
Pressure Core Spray Jockey
Pumps Suction Strainers
Requiring Cleaning
Reference: LER 82-094/03 L-0
AECM-82/552

During performance of the LPCS Monthly Functional Test, the suction strainers for the Low Pressure Core Spray Jockey Pumps required cleaning. To clean the strainers, the Jockey Pump and LPCS Pump Breakers were racked out which resulted in LPCS being inoperable per T.S.3.5.1.a.1. Attached is LER 82-094/03 L-0.

Yours truly,

J.P. McGaughey
For J. P. McGaughey

JPM:sap
Attachment

- cc: Mr. N. L. Stampley (w/a)
- Mr. R. B. McGehee (w/o)
- Mr. T. B. Conner (w/o)
- Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

OFFICIAL COPY
IE 22

8211230263 821116
PDR ADOCK 05000416
S PDR