

30-3489

NOV 19 1982

Elmbrook Memorial Hospital  
ATTN: Mr. Robert McGlynn  
Administrator  
19333 W. North Avenue  
Brookfield, WI 53005

License No. 48-13463-01

Gentlemen:

This refers to the routine safety inspection conducted by Mr. R. E. Burgin of this office on November 8, 1982, of activities authorized by NRC Byproduct Material License No. 48-13463-01 and to the discussion of our findings with you and Ms. P. Klapperich at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

In addition to the above areas, the inspector examined actions described in your letter dated November 16, 1979, regarding an apparent item of non-compliance found during our October 1979 inspection. We have no further questions regarding this matter.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

*for* D. G. Wiedeman, Chief  
Materials Radiation Protection  
Section 1

cc: DMB/Document Control Desk (RIDS)

R111  
*RFB*  
Burgin/np  
11/17/82

R111  
*RFB*  
Wiedeman

IE HQ FILE COPY

8211230375 821119  
NMS LIC30  
48-13463-01 PDR

DMB: IE07