

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50-247
 UNIT NAME Indian Point
 DATE 9/7/82
 COMPLETED BY E. Fich
 TELEPHONE 914-526-5155

REPORT MONTH August 1982

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
6	8/12/82	F	13.38	A	1	NONE	CB	Pump XX, B	Indication of controlled leakage seal failure on No. 22 RCP.
N/A	8/13/82	S	56.68	B	4	82-031-99X	SB	HTEXCH. C	Unit shutdown extended for Fan Cooler Unit Repairs.

¹
 F: Forced
 S: Scheduled

²
 Reason:
 A-Equipment Failure (Explain)
 B-Maintenance or Test
 C-Refueling
 D-Regulatory Restriction
 E-Operator Training & License Examination
 F-Administrative
 G-Operational Error (Explain)
 H-Other (Explain).

³
 Method:
 1-Manual
 2-Manual Scram.
 3-Automatic Scram.
 4-Other (Explain)

⁴
 Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NEI 0161)

⁵
 Exhibit I - Same Source

(9/77)

8211230399 821115
 PDR ADDCK 05000247
 PDR