

NOV 19 1982

Wormald, U.S.
Ansul Chemical Division
ATTN: Dr. Leonard Moore
One Stanton Street
Marinette, WI 54143

License No. 48-19829-02

34-1817L

Gentlemen:

This refers to the routine safety inspection conducted by Mr. D. R. Gibbons and Ms. R. M. Douglas of this office on November 8, 1982, of activities authorized by NRC Byproduct Material License No. 48-19829-02 and to the discussion of our findings with you and Mr. S. W. Hansen at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as described in the enclosed Appendix. The inspection showed that action had been taken to correct the identified noncompliance and to prevent recurrence. Consequently, no reply to this noncompliance is required and we have no further questions regarding this matter at this time.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1

Enclosure: Appendix,
Notice of Violation

cc w/encl:
DMB/Document Control Desk (RIDS)

RIII
REB for
Gibbons/np
11/17/82

RIII
REB for
Douglas

RIII
REB for
Wiedeman

IE HQ FILE COPY

8211230413 821119
NMS LIC30
48-19829-02 PDR

DMB:IE07