

Appendix

NOTICE OF VIOLATION

Commonwealth Edison Company

Docket No. 50-304

As a result of the inspection conducted on September 1 through October 15, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

Zion Technical Specification 3.9.5.d states: "Positive reactivity changes shall not be made by boron dilution when the containment integrity is not intact unless the reactor is maintained subcritical by at least 10%  $\Delta K/K$ ."

Contrary to the above, on September 28, 1982, a positive reactivity change by boron dilution was made with containment integrity not intact and with the reactor subcritical by less than 10%  $\Delta K/K$ .

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

\_\_\_\_\_  
Dated

\_\_\_\_\_  
R. L. Spessard, Director  
Division of Project and  
Resident Programs