Duquesne Light Company Beaver Valley Power Station PO. Box 4 Shappingport, PA 15077/0004

JOHN D. STEBER Vice President - Nuclear Group

February 8, 1991

14127 160 526

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

Reference: Beaver Valley Power Station, Unit No. 2

Docket No. 50-412, License No. NPF-73

Subject: Second Refueling Outage Inservice Inspection Report

This letter forwards the Inservice Inspection Report on ASME Class 1, 2, and 3 components examined during the second refueling outage at Beaver Valley Unit No. 2. The ASME Boiler and Pressure Vessel Code, Section XI, Article IWA-6230 requires that an inservice inspection report be submitted to the enforcement and regulatory authority having jurisdiction at the plant site within ninety (90) days after completion of an inservice inspection. The latest inservice inspections at Beaver Valley Unit No. 2 were completed on November 15, 1990.

These examinations are part of Interval 1, Period 1 of the Beaver Valley Unit No. 2 ISI inspection schedule. The inservice inspections were performed in accordance with Section XI of the ASME Boiler and Pressure Vessel Code, 1983 edition through Summer 1983 agenda.

Please contact me or members of my staff if you have any questions regarding the attached report.

Sincerely,

O. D. Sieber Vice President Nuclear Group

Attachment

cc: Mr. J. Beall, Sr. Resident Inspector

Mr. T. T. Martin, NRC Region I Administrator

Mr. A. W. DeAgazio, Project Manager

9102260108 910208 PDR ADOCK 05000412 Q PD'( floan