

DEPARTMENT OF THE ARMY HEADQUARTERS, U. S. ARMY MATERIEL COMMAND 5001 ECENHOWER AVENUE, ALEXANDRIA, VA 22333-0001

December 17, 1990



Safety Office

U.S. Nuclear Regulatory Commission Region III ATTN: Materials Licensing Branch 799 Roosevelt Road Glen Ellyn, Illinois 60137

Reference: NRC Docket No. 04008835; License 3TB-1433 - AMCSF-P/90-0235/0236

Dear Mr. Davis:

Forwarded are four copies of the U.S. Army Aviation Systems Command's response to your letter dated November 2, 1990 which enclosed the demand for information and requested a Statement of Intent. The enclosed letter is also the correspondence which I indicated would be forthcoming in my letter dated November 30, 1990.

I hope this responds to your request for information.

Please acknowledge receipt of correspondence on the enclosed DA Form 208, Delay, Referral or Follow-Up Notice. If you have any questions, please contact the undersigned at 703 274-9340.

Sincerely,

flor

Patricia A/Elker Chief, Health Physics Safety Office

Enclosures

Copies Furnished:

Director, Division of Low Level Waste Management and Decommissioning, Office of Nuclear Material Safety and Safeguards, Washington, D.C. 20555 HQDA(SGPS-PSP-E) Commander, AVSCCM, ATTN: AMSAV-X

Director, USAMC Field Safety Activity, ATTN: AMXOS

RECEIVED DEC 24 1990 REGION III

DEC 2 / 1000

DEPARTMENT OF THE ARMY HEADQUARTERS, US ARMY AVIATION SYSTEMS COMMAND 4300 GOODFELLOW BOULEVARD, ST. LOUIS, MO 63120-1798

REPLY TO ATTENTION OF

AMSAV-X

"10 DEC

MEMORANDUM THRU COMMANDER, U. S. ARMY MATERIEL COMMAND, ATTN: AMCSF, 5001 EISENHOWER AVE, ALEXANDRIA, VA 22333-0001

FOR REGIONAL ADMINISTRATOR, U. S. NUCLEAR REGULATORY COMMISSION REGION III, 799 ROOSEVELT RD, GLEN ELLYN, ILL 60137

SUBJECT: Decommissioning Financial Assurance/Statement of Intent

1. References:

a. U. S. Nuclear Regulatory Commission (NRC) License STB-1433/Docket 04008835.

b. Title 10, Code of Federal Regulations, Section 40.36 (10 CFR 40.36).

2. The U. S. Army possesses magnesium-thorium alloy aircraft engine parts, possession of which are exempt from licensing pursuant to 10 CFR 40.13(c)(4). The U. S. Army Aviation Systems Command (AVSCOM) obtained the referenced license to authorize aviation intermediate maintenance and designated aviation unit maintenance activities to effect minor repairs of these license exempt aircraft parts. This maintenance is limited to operations associated with the replacement of helicoil inserts and treatment of small areas of corrosion.

3. As only license exempt magnesium-thorium alloys are possessed, the thorium is not in a readily dispersible form, and maintenance is limited to small quantities and irregular frequencies, the provisions of 10 CFR 40.36(b) should not apply. A "Statement of Intent" is hereby rendered, however, pursuant to 10 CFR 40.36(e)(4) to assure compliance with reference 1b above.

4. The following information is provided pursuant to NUREG-1337:

a. This statement specifically includes all aviation units authorized by AVSCOM to perform NRC licensed aircraft engine maintenance in accordance with the provisions of NRC Source Material License STE-1433.

"IT DEC 1000

AMSAV-X

-

SUBJECT: Decommissioning Financial Assurance/Statement of Intent

b. No contaminated facilities currently exist or are anticipated. Therefore, no decommissioning costs are expected. In the event that operations performed pursuant to STB-1433 result in contamination of a facility, AVSCOM will expeditiously request funding to effect decontamination.

5. The foregoing Statement of Intent is provided by me in my capacity as Commander, AVSCOM and as the individual with authority to sign the statement on behalf of the U.S. Army.

 Point of contact for this action is Mr. Chambers, phone (314) 263-3524 (DSN 693-3524).

Donald R Willixm som

DONALD R. WILLIAMSON Major General, USA Commanding