



PILGRIM NUCLEAR POWER STATION
RFD No. 1 ROCKY HILL ROAD
PLYMOUTH, MASSACHUSETTS 02360

November 10, 1982

BECo Ltr. #82-290

C. J. MATHIS
STATION MANAGER
PILGRIM STATION

Ronald C. Haynes
Regional Administrator, Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Docket Number 50-293
License DPR-35

Dear Sir:

The attached Licensee Event Report 82-046/01T-0, "HPCI MOV 2301-3 Steam Leak", is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B.1.e.

BECo believes that the intent of Regulatory Guide 1.16 Section 2.9.5.c, which provides guidance on determining reportability of events per the Technical Specification referenced above, is to report promptly those events where redundancy is not available. Therefore, in the future PNPS will report events of this nature in accordance with 6.9.B.2.b of the Technical Specifications.

If there are any questions on this subject, please contact us.

Respectfully submitted,

C. J. Mathis
Station Manager
Pilgrim Station

GGW:ep

Enclosure: LER 82-046/01T-0

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Standard BECo LER Distribution

8211290305 821110
PDR ADOCK 05000293
S PDR

IEU