William S. Orser Senior Vice President

Fermi 2 6400 North Dixle Highway Newport, Michigan 48166 (313) 586-5201



February 19, 1991 NRC-91-0023

U. S. Nuclear Regulatory Commission Atta: Document Control Desk Washington, D. C. 20555

References:

- 1) Fermi 2 NRC Docket No. 50-341 NRC License No. NPF-43
- 2) NRC Letter to Detroit Edison,
 "Initial and Requalification Retake
 Examination Report," dated
 January 22, 1991 (Examination
 Report No. 50-341/CL-90-03)

Subject:

Response to Programmatic Concern with Examination Security

Detroit Edison has reviewed the NRC Examination Report provided by Reference 2, which was received on January °5, 1991. The examination report discusses a concern in the area of a unination security which was identified prior to the examination administration and requests a response within 30 days of the date of the NRC letter (Reference 2). This letter provides the requested response.

Detroit Edison has evaluated the concern and taken corrective actions to prevent recurrence, as given below:

- O A Human Performance Evaluation System (HPES) (Report No. 90-017) was performed to identify the causal factors contributing to the event and the corrective action required.
- o The Operations Training Work Leader was counseled on methods of effective communications and work direction.
- An Operations Training Programs Guideline (OTG-15),
 "Security Agreement Clarification" was issued to assure that
 the security agreement is thoroughly understood when signed.
- Operations Training personnel have read HPES Report 90-017 and OTG-15.

18hed.
-017
Ald: Ne (045) 8560

USNRC February 19, 1991 NRC-91-0023 Page 2

o Additional training was provided on examination security as part of the 4th Quarter Instructor "tinuing Training Session, and OTG-15 las been revise to include personnel other than instructors who may be resided to sign security agreements.

If you have any questions, please call Mr. Frederick E. Abramson at (313) 586-4143.

Sincerely,

cc: A. B. Davis

R. W. DeFayette

W. G. Rogers

J. F. Stang

USNRC Region III