

November 19, 1982

.

Log No. K82-1650 File: RR2 (NP-33-82-66)

Docket No. 50-346 License No. NPF-3

Mr. James G. Keppler Regional Administrator, Region III Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

LER No. 82-055 Davis-Besse Nuclear Power Station Unit 1 Date of Occurrence: October 21, 1982

Enclosed are three copies of Licensee Event Report 82-055 which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Teny Doming

Terry D. Murray Station Superintendent Davis-Besse Nuclear Power Station

TDM/1jk

8211290535 821119 PDR ADOCK 05000346

Enclosures

cc: Mr. Richard DeYoung, Director Office of Inspection and Enforcement Encl: 30 copies

> Mr. Norman Haller, Director Office of Management and Program Analysis Encl: 3 copies

Mr. Tom Peebles NRC Resident Inspector Encl: 1 copy

NOV- 2 2 1982

THE TOLEDO EDISON COMPANY EDISON PLAZA 300 MADISON AVENUE TOLEDO, OHIO 43652

PDR

