TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

November 18, 1982

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE REPORT SQR0-50-327/82126

The enclosed report provides details concerning the failure of the check valve downstream of the main steam isolation valve. This report is submitted in accordance with Sequoyah unit 1 Technical Specification 6.9.1.12.i.

Very truly yours,

TENNESSEZ VALLEY AUTHORITY

H. J. Green

Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Records Center Institute of Nuclear Power Operations Suite 1500 1100 Circle 75 Parksay Atlanta, Georgia 30339

NRC Inspector, Sequoyah

OFFICIAL COPY