



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
789 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

DCD/ACB
(RIDS)

FEB 20 1991

Docket No. 50-454
Docket No. 50-455

Commonwealth Edison Company
ATTN: Mr. Cordell Reed
Senior Vice President
Opus West III
1400 Opus Place
Downers Grove, IL 60515

Gentlemen:

This refers to the routine safety inspection conducted by Mr. W. J. Kropp, and Ms. D. R. Calhoun of this office from January 3 through February 11, 1991, of activities at the Byron Station, Units 1 and 2, authorized by NRC Operating Licenses No. NPF-37 and No. NPF-66, and to the discussion of our findings with Mr. R. Pleniewicz and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

W D Shafer
W. D. Shafer, Chief
Reactor Projects Branch 1

Enclosure: Inspection Reports
No. 50-454/91002(DRP);
No. 50-455/91002(DRP)

See Attached Distribution

IE01

9102270361 910220
PDR ADDCK 05000454
Q PDR
260125

Distribution

cc w/enclosure:

M. Wallace, Vice President,
PWR Operations
T. Kovach, Nuclear
Licensing Manager
T. Schuster, Nuclear Licensing
Administrator
R. Pleniewicz, Station Manager
D. Brindle, Regulatory Assurance
Supervisor
DCD/DCB (RIDS)
OC/LFDCB
Resident Inspector: Byron,
Braidwood, Zion
Richard Hubbard
J. W. McCaffrey, Chief, Public
Utilities Division
Diane Chavez, DAARE/SAFE
T. Hsia, LPM, NRR
Robert Newmann, Office of Public
Counsel, State of Illinois Center